[redacted]	**INSPECTION REPORT** *THIS DOCUMENT IS NON-NEGOTIABLE*	**Client Name**	-
		Report No.	
		Inspection Date	Mar 23rd,2026

By:	[redacted]	**To:**	-
Contact:	[redacted]	**Contact:**	
E-mail:	[redacted]	**Location:**	Shenzhen, Guangdong, China
Inspector:	Tommy	**Weather:**	Sunny

I. GENERAL INFORMATION

		Product Photo
Supplier:	Shing Yip Gifts (Dongguan) Company Ltd	
Manufacturer:	Shing Yip Gifts (Dongguan) Company Ltd	
Product Name:	PTNSB104 Bebefinn Big flap sound book #2	
PO No.:	N/A	
Item No.:	N/A	
Order Quantity:	5000pcs	
Order unit:	☒ Pcs. ☐ Set ☐ other. Specify:	
Inspection Quantity:	5000pcs	
Reference Sample:	Yes, Sample provided by factory	
Inspection Type:	**Re-inspection**	

II. OVERALL INSPECTION CONCLUSION

PENDING

GUIDED IMPORTS PTE. LTD. UEN No.: 202004904H

Approved by: [redacted], Quality Management Officer

PASSED	-	Conform to Client's Requirement
PASSED (Conditional)	-	The Passed results will be valid only **after the client is informed and accepts** the issues in the remarks
PENDING	-	Subject to Client's Evaluation
FAILED	-	Not Conform to Client's Requirement

AQL DETAILS

Inspection Standard: ANSI/ASQ Standard Z.1.4 / ISO 2859-1		**Defects**		
		Critical	**Major**	**Minor**
Sampling Plan: Normal, Single	**AQL**	**0**	**2.5**	**4.0**
Inspection Level: II	**Defects Found:**	**0**	**1**	**12**
Sample Size: 200pcs	**Max. Allowed:**	**0**	**10**	**14**
RESULT	☒ PASSED ☐ FAILED ☐ PENDING			

- Based on the inspection results, the estimated defective rate in this item's consignment is **6.5**% (Critical defective rate: 0 %, Major defective rate: 0.5%, Minor defective rate: 6%).

[redacted]	**INSPECTION REPORT** *THIS DOCUMENT IS NON-NEGOTIABLE*	**Client Name**	-
		Report No.	
		Inspection Date	Mar 23rd,2026

III. INSPECTION SUMMARY

Category	PASSED*	FAILED	PENDING	N/A
Quantity (Part A)	☐	☐	☒	☐
Workmanship (Part B)	☒	☐	☐	☐
On-Site Test (Part C)	☒	☐	☐	☐
Product Specification (Part D)	☒	☐	☐	☐
Packaging (Part E)	☐	☐	☒	☐
Marking & Label & Accessories (Part F)	☐	☐	☒	☐
Client Special Requirement (Part G)	☐	☐	☐	☒


* The Passed results will be valid only **after the client is informed and accepts** the issues in the following remarks.


IV. REMARKS


	Problem Remarks
1	The weight and packing need client to confirm.
2	All products were no packing.
3	The proportion of edge cutting defects is 100%, which is the same as the sample
	General Remarks
4	All defects have been picked out.


	Mold/Corrosion risk assessment – expected results:	RISK rating (High / Low / No)
5	**Product:** The product should not have any moisture visually present, no odor due to moisture and no moisture that can be felt when rubbing your hand across the product.	☐High ☐Low ☒No
6	**Product:** The actual result of the moisture content test should not exceed the maximum content allowed (For wooden / Bamboo / Rattan / Fabric / Leather products).	☐High ☐Low ☒No
7	**High water absorptive product:** The product should be packed airtight, desiccant should be used in the packaging and shipment container to prevent mold.	☐High ☐Low ☒No
8	**Iron product:** The iron material should be protected with coating / paint on the surface to prevent the mold.	☐High ☐Low ☒No
9	**Package:** At least one mold prevention unit in the packaging (ex: Silica gel, Micro Pak, Super Dry, etc.).	☐High ☐Low ☒No
10	**Cartons:** Should be inside of the warehouse/factory on pallets (no contact with walls/floor), dry (check the bottom of cartons) and without moisture or odor.	☐High ☐Low ☒No
11	**Storing conditions of cartons, products, fabric, material:** Should be clean, dry, with ventilation and without mold/water on walls. Goods should not be stored in direct sunlight or elevated heat conditions and away from open windows.	☐High ☐Low ☒No
12	**Relative humidity in storing area:** Check factory's hygrometer. The relative humidity should be < 70%. If there is not any factory's hygrometer, pick "N/A".	☐High ☐Low ☐No ☒N/A
	Factory Information:	
13	**Factory cooperation:** ☐ **Good** – Clean work environment, enough manpower to assist, and good cooperation. ☒ **Average** – Somewhat clean environment, enough manpower to assist, enough cooperation. ☐ **Poor** – Not-clean work environment / little Manpower and equipment / document not provided timely.	

	Reason:
14	**Inspector's opinion on the factory:** ☐ **Good** - The factory was neat and tidy. The testing equipment was well maintained and calibrated. ☒ **Average** - The factory was tidy, and the testing equipment ran normally. ☐ **Poor** - The factory was messed; the basic testing equipment was not available / defective.
Sample Collection Record:	
15	☒ No samples collected on site / ☐ One sample collected on site
Remark Photos:	









Remark 3: The proportion of edge cutting defects is 100%, which is the same as the sample

[redacted]	**INSPECTION REPORT** *THIS DOCUMENT IS NON-NEGOTIABLE*	**Client Name**	-
		Report No.	
		Inspection Date	Mar 23rd,2026

PART A - QUANTITY CHECKING								
Item	Order Qty	Qty/Carton	Order Cartons	Quantity Breakdown			Sample Size	
				Packed	Unpacked	Unfinished	Packed	Unpacked
PTNSB104	5000	N/A	N/A	0	5000	0	0	200
Total:	5000	N/A	N/A	0	5000	0	0	200

Selected Cartons:		
Topic	All items	N/A
Qty of cartons Item 1 selected randomly on site:	200pcs	N/A
Carton No.:	N/A	N/A

Spare Parts & Quantity Check:		
Were there any spare parts on site for checking?	☐ Yes	☒ No
Did the spare parts quantity conform to the client's list/specification?	☐ Yes	☒ No
Result: ☐ **PASSED** ☐ **FAILED** ☒ **PENDING**		
Remark:	-All products were no packing.	

[redacted]	**INSPECTION REPORT** *THIS DOCUMENT IS NON-NEGOTIABLE*	**Client Name**	-
		Report No.	
		Inspection Date	Mar 23rd,2026

PART B - WORKMANSHIP				
Defect Description		**Critical**	**Major**	**Minor**
For itemPTNSB104, Sample size:200pcs				
1	Poor trimming	**0**	**0**	**3**
2	Poor cutting edge	**0**	**0**	**2**
3	Dirty mark	**0**	**0**	**3**
4	Adhesive stains	**0**	**0**	**1**
5	Black dot	**0**	**0**	**2**
6	Surface wrinkles	**0**	**0**	**1**
7	Surface delamination	**0**	**1**	**0**
	Total Defects Found:	**0**	**1**	**12**
	Defect Max. Allowed:	**0**	**10**	**14**
	Sample size:	**200**	**200**	**200**
	Inspection Result:	**Passed**	**Passed**	**Passed**

Result: ☒ **PASSED** ☐ **FAILED** ☐ **PENDING**

Remark:	N/A

Note: A Defective is defined as a unit of product that contains one or more defects.


A Defect is defined as any non-conformance of the inspected unit of product with specified requirements.

→ A single defect is taken into account per each defective unit; only one most serious defect is taken into account per each defective unit.

Defect photos of Item No. 1: PTNSB104



Poor trimming



Poor trimming

[redacted]	**INSPECTION REPORT** *THIS DOCUMENT IS NON-NEGOTIABLE*	**Client Name**	-
		Report No.	
		Inspection Date	Mar 23rd,2026




Poor trimming




Poor cutting edge



Poor cutting edge




Dirty mark



Dirty mark



Dirty mark



Adhesive stains



Black dot



Black dot



Surface wrinkles



Surface delamination

-

[redacted]	**INSPECTION REPORT** *THIS DOCUMENT IS NON-NEGOTIABLE*	**Client Name**	-
		Report No.	
		Inspection Date	Mar 23rd,2026

PART C - ON-SITE TESTS					
IL-S-2, RIGID-General, AQL-4.0					
	Description	**Level**	**Sample Size**	**Test Result**	**Remarks**
1	Function check	-	100pcs	☒PA ☐F ☐PE	N/A
2	Smell check	G-II	200pcs	☒PA ☐F ☐PE	N/A
3	Barcode Readability Check	S-2	8pcs	☒PA ☐F ☐PE	N/A
Result: ☒ **PASSED** ☐ **FAILED** ☐ **PENDING**					
Remark:	N/A				


Drop Test Height			
English		Metric	
Package Weight (lb)	Drop Height (in)	Package Weight (kg)	Drop Height (cm)
1 – 20	30	1 – 9	76
21 – 40	24	10 – 18	61
41 – 60	18	19 – 27	46
60 – 100	12	28 – 45	30
101 – 150	8	46 – 68	20

PART D - SPECIFICATION CHECKING					
	Client's Spec.	**Ref. Sample**	**1# Sample**	**2# Sample**	**3# Sample**
Item No.: PTNSB104					
Product size L x W x H (mm)	N/A	24.5*30*2.51	24.5*30*2.51	24.5*30*2.51	24.5*30*2.51
Product Net Weight (kg)	N/A	0.66	0.74	0.74	0.72
Result: ☒ **PASSED** ☐ **FAILED** ☐ **PENDING**					
Remark:	N/A				

[redacted]	**INSPECTION REPORT** *THIS DOCUMENT IS NON-NEGOTIABLE*	**Client Name**	-
		Report No.	
		Inspection Date	Mar 23rd,2026

PART E - PACKING CHECKING

Package Detail



Item No.	Qty / Inner Box		Carton Size (L × W × H, cm)		Gross Weight (kg)		Qty / Carton	
	Spec.	Actual	Spec.	Actual	Spec.	Actual	Spec.	Actual
PTNSB104	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Export Carton Details			
Fastening Metal Staples	N/A	Nylon Band	N/A
Material	N/A	Corrugated Paper Plies	N/A

Packing Method:

N/A

Assortment Method:

N/A

Result: ☐ PASSED ☐ FAILED ☒ PENDING

Remark:	-All products are not packing

[redacted]	**INSPECTION REPORT** *THIS DOCUMENT IS NON-NEGOTIABLE*	**Client Name**	-
		Report No.	
		Inspection Date	Mar 23rd,2026


PART F – MARKING & LABELS & ACCESSORIES				
Barcode/Label/Printing				
Name	**Location**	**Spec.**	**Actual finding**	**Result**
Item No.: PTNSB104				
Barcode	☐ Product	8809456157496	8809456157496	☒PA ☐F ☐PE
QR code	☐ Product			☐PA ☐F ☒PE
Accessories check				
N/A				☐PA ☐F ☐PE
Shipping Marks				
Shipping Marks (on Side)				☐PA ☐F ☒PE
Side Marks (on Side)				☐PA ☐F ☒PE
Inner Box Marks (on Side)				☐PA ☐F ☐PE
Result: ☐ **PASSED** ☐ **FAILED** ☒ **PENDING**				
Remark:	-All products are not packing			

PART G - CLIENT SPECIAL REQUIREMENTS		
	Client Requirements	**Result**
1	N/A	☐PA ☐F ☐PE
Result: ☐ **PASSED** ☐ **FAILED** ☐ **PENDING**		
Remark:	N/A	


	INSPECTION REPORT *THIS DOCUMENT IS NON-NEGOTIABLE*	**Client Name**	-
		Report No.	
		Inspection Date	Mar 23rd,2026

PART H. PHOTOS

PTNSB104



Product view(11)



Product view(12)




Product view(13)



Product view(14)



Product view(15)



Product view(16)

[redacted]	**INSPECTION REPORT** *THIS DOCUMENT IS NON-NEGOTIABLE*	**Client Name**	-
		Report No.	
		Inspection Date	Mar 23rd,2026




Product view(17)



Product view(18)



Product view(19)



Product view(20)



Product view(21)



Product view(22)

	INSPECTION REPORT *THIS DOCUMENT IS NON-NEGOTIABLE*	**Client Name**	-
		Report No.	
		Inspection Date	Mar 23rd,2026



Product view(23)



Product view(24)




Product view(25)



Product view(26)



Product view(27)



Product view(28)

[redacted]	**INSPECTION REPORT** *THIS DOCUMENT IS NON-NEGOTIABLE*	**Client Name**	-
		Report No.	
		Inspection Date	Mar 23rd,2026



Product view(29)



Product view(30)



Product view(31)



Product view(32)



Product view(33)



Product view(34)

Others



Warehouse



Warehouse



Warehouse



Warehouse



Warehouse



Inspection on-site

PART I - ANTI-BRIBERY LETTER

GuidedImports

ANTI - BRIBERY LETTER / 廉正声明

To: Client / Supplier / Manufacturer / Warehouse Manager,
本公司致客户/供应商/厂家/仓库管理人员

Guided Imports anti-bribery and corruption policy reinforces our obligation and purpose to act honestly and ethically in all our business transactions. 坤盛进出口公司的反贿赂和腐败政策加强了我们的责任和目的使我们更诚信道德地对待所有的业务。

We will not seek to influence others, either directly or indirectly, by paying or receiving bribes or kickbacks, or by any other means that is considered unethical, illegal or harmful to our reputation for honesty and integrity. 我们不会试图直接或者间接的去影响他人例如贿赂或者收回扣或者其他不道德的违法的有损我们信誉或者名声的手段。

Employees and representatives of the company are expected to decline anything including but not limited to cash, expenses, commission, samples, gifts, catalogs, or any other things of value. We hereby appreciate your cooperation to monitor our inspector.公司员工和代表希望拒绝接受一切有价值的东西比如现金/津贴/佣金/样品/礼物商品清单等等。

If our inspector is offered a bribe by a person or entity doing business with the company, they are required to report it immediately. 我们特此感谢您合作监督我们的检察员。如果我们的检察员收到了私人或者公司生意上的贿赂他们会立刻报告这件事情。

Please copy this letter for future reference.
➢本廉正单请贵公司复印留底
We hereby remind that our inspector is not the final decision maker who should be the client. Our report does not give permission to release the goods for shipment.
➢我们在此提醒贵方我们的检验员与审核员不是最终决定人最终决定由客人裁决本报告不授权出货。

负责人签字并盖公章
SIGNATURE AND CHOP 杨定生

日期26年3月23日
DATE:

Guided Imports Quality Inspection Service | www.guidedimports.com

Note:

1. The Passed results will be **valid only after the client is informed and accepts the issues** in the following remarks
2. This report reflects our findings at time and place of inspection.
3. This report does not relieve suppliers from their contractual liabilities or prejudice buyers' right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter.
4. This report does not evidence shipment.

---- END OF THE REPORT ----